

# ASSEMBLY INSTRUCTION

## CP1110-F-1098



A x20  
Spec:  $\varnothing 8 \times 44$



B x20  
Spec:  $\varnothing 25 \times 8$



C x20  
Spec:  $\varnothing 10 \times 18$




D x20  
Spec:  $\varnothing 12 \times \varnothing 10 \times 11$



E x1  
Spec: 5#



FIG. 1



**FIG.**  
**2**

