





45 min




x1




x2



1 x1



2 x1




3 x2




4 x2



5 x2




6 x1




A x2



B x4



C x2



D x2




E x6



F x1




G x1






1

C  xO


E  xO




Atención a la dirección de la pata.  
Un mal montaje puede ocasionar la rotura de la pata.  
Attention to the assembling of the leg.  
A wrong assembling can end in a broken leg.




2


B  x4






3


A  x2


E  x2






4

E  x2


D  x2







5







**JULIÀ GRUP Furniture Solutions S.L.**

B-17616277

Pol. Ind. Bosc d'en Cuca

C / Tallers, 14

17410 Sils SPAIN

[contact@kavehome.com](mailto:contact@kavehome.com)